



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	35	Date:	8/19/2004	MeterBasin:	01_WR18
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2604		Ken Oak	ROAD

Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	75	

Comments: holes in ground

SMOKE TEST PHOTOS



Photo No: 4

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_B\B_2004_0819Image0004.JPG

Image Status: Image found and displayed.



Photo No: 5

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_B\B_2004_0819Image0005.JPG

Image Status: Image found and displayed.



Photo No: 6

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_B\B_2004_0819Image0006.JPG


Image Status: Image found and displayed.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 35

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\35.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	35	Date:	8/19/2004	MeterBasin:	01_WR18
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5504		Stuart	AVE

Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	75	

Comments: holes in ground

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 7

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_B\B_2004_0819Image0007.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 35

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\35.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	35	Date:	8/19/2004	MeterBasin:	01_WR18
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2600		Ken Oak	ROAD

Source Type:	18= Other	Location:	7=Yard-Front	Severity:
Sector:	1=Public	Drainage Area:	25	
Comments:	holes in ground			

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 8

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_B\B_2004_0819Image0008.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 35

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\35.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	35	Date:	8/19/2004	MeterBasin:	01_WR18
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	4	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:	
2600		Ken Oak	ROAD	
Source Type:	01= Main Sewer	Location:	2=Paved Asphalt	Severity:
Sector:	1=Public	Drainage Area:	0	
Comments:	manhole			

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 9

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_B\B_2004_0819Image0009.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 35

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\35.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	36	Date:	8/19/2004	MeterBasin:	01_WR19
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2712		Manhattan	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	50	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 7

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_A\A_2004_0819Image0007.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 36

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\36.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	36	Date:	8/19/2004	MeterBasin:	01_WR19
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	4	Priority CCTV:	

House Number	5609	Street Prefix:		Street Name:	Merville	Street Type:	AVE
Source Type:	18= Other	Location:	14=Other	Severity:			
Sector:	2=Private	Drainage Area:	0				
Comments:	Plumbing vent						

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 8

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_A\A_2004_0819Image0008.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 36

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\36.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	36	Date:	8/19/2004	MeterBasin:	01_WR19
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5605		Merville	AVE

Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	50	

Comments: hole grd.

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 9

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_A\A_2004_0819Image0009.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 36

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\36.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	36	Date:	8/19/2004	MeterBasin:	01_WR19
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5610		Merville	AVE

Source Type:	02= Service Line	Location:	9=Yard-Side	Severity:
Sector:	2=Private	Drainage Area:	50	

Comments: hole in ground between curb and sidewalk

SMOKE TEST PHOTOS




Photo No: 10

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_B\B_2004_0819Image0010.JPG

Image Status: Image found and displayed.



Photo No: 28

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\Retakes\UTID36-B1_2005_0523Image028.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

36

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\36.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	37	Date:	8/19/2004	MeterBasin:	01_WR19
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	5	Priority CCTV:	

House Number	5609	Street Prefix:		Street Name:	Woodcrest	Street Type:	AVE
Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:			
Sector:	2=Private	Drainage Area:	25				
Comments:							

SMOKE TEST PHOTOS



Photo No:
Filename Path:

Image Status: No image name specified.

Photo No: 10

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_A\A_2004_0819Image0010.JPG

Image Status: Image found and displayed.

Photo No:
Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 37

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\37.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	37	Date:	8/19/2004	MeterBasin:	
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	0	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
---------------------	-----------------------	---------------------	---------------------

Source Type:	Location:	Severity:
Sector:	Drainage Area: 0	
Comments: No defects observed		

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

37

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\37.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	38	Date:	8/19/2004	MeterBasin:	01_WR20
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2901		Whitney	AVE

Source Type:	18= Other	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	100	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 11

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_A\A_2004_0819Image0011.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 38

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\38.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	38	Date:	8/19/2004	MeterBasin:	01_WR20
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	Y
Defect No:	2	Setup No:	6	Priority CCTV:	

House Number	2901	Street Prefix:		Street Name:	Whitney	Street Type:	AVE
Source Type:	09= Stairwell Drain	Location:		2=Paved Asphalt	Severity:		
Sector:	2=Private	Drainage Area:		20			
Comments:							

SMOKE TEST PHOTOS



Photo No:
Filename Path:

Image Status: No image name specified.

Photo No: 12

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_A\A_2004_0819Image0012.JPG

Image Status: Image found and displayed.

Photo No:
Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 38

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\38.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	38	Date:	8/19/2004	MeterBasin:	01_WR19
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2805		Whitney	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	100	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 11

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0819-2004\T-1\PLAYER_B\B_2004_0819Image0011.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 38

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\38.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	38	Date:	8/19/2004	MeterBasin:	01_WR19
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2807		Whitney	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	100	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 12

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_B\B_2004_0819Image0012.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 38

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\38.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	39	Date:	8/19/2004	MeterBasin:	
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	0	Setup No:	7	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
---------------------	-----------------------	---------------------	---------------------

Source Type:	Location:	Severity:
Sector:	Drainage Area: 0	
Comments: No defects observed		

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 39

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\39.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	39	Date:	8/19/2004	MeterBasin:	01_WR20
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	7	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2900		W Rogers	AVE

Source Type:	04= Cleanout	Location:	5=Sidewalk	Severity:
Sector:	1=Public	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 13

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_B\B_2004_0819Image0013.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 39

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\39.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	40	Date:	8/19/2004	MeterBasin:	
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	0	Setup No:	8	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
--------------	----------------	--------------	--------------

Source Type:	Location:	Severity:
Sector:	Drainage Area: 0	
Comments:	No defects observed	

SMOKE TEST PHOTOS

Photo No:
Filename Path:
Image Status: No image name specified.

Photo No:
Filename Path:
Image Status: No image name specified.


Photo No:
Filename Path:
Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 40

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\40.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	40	Date:	8/19/2004	MeterBasin:	01_WR20
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	8	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3100		W Rogers	AVE

Source Type:	18= Other	Location:	14=Other	Severity:	4=Major
Sector:	1=Public	Drainage Area:	0		

Comments: Electric conduit - at utility pole - direct connection - needs futher evaluation.

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 14

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0819-2004\T-1\PLAYER_B\B_2004_0819Image0014.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 40

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\40.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	41	Date:	8/20/2004	MeterBasin:	01_WR18
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5813		Stuart	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	25	

Comments:

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 1

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0820-2004\T-1\PLAYER_A\A_2004_0820Image0001.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 41

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\41.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	41	Date:	8/20/2004	MeterBasin:	01_WR18
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5816		Stuart	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	25	

Comments:

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 2

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0820-2004\T-1\PLAYER_A\A_2004_0820Image0002.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 41

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\41.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.